Name of the work: Construction of Dialysis centre at Mallasandra in ward No:13

a) PCC 1:3:6 after.

b) Earthwork in Hard rock.

c) Column marking is shown.

EE inspecting site.

(b)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಆಯೋಜನಾ ವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Name of the work: Construction of Dialysis centre at Mallasandra in ward No:13

Consultant inspecting steel fabrication for doors and footing

"steel fabrication for Combined footing"

(8)

Scanned by CamScanner

Name of the work: Construction of Dialysis centre at Mallasandra in ward No:13

4 pcs in my opinion laid for plinth beams

Shuttering works completed for plinth beams

13

Scanned by CamScanner

Name of the work: Construction of Dialysis centre at Mallasandra in ward No:13

" Curing for RCC slab in progress"

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯೋಜನಾ ವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು

(18)

Scanned by CamScanner